

Book

Supplemental Type Certificate

Number **ST00802SE**

This certificate, issued to

**LifePort, Inc.
1610 Heritage Way
Woodland, WA 98674**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: A10CE
Make: Learjet
Model: 35, 35A

Description of the Type Design Change: Installation of emergency medical stretcher and base, oxygen and electrical systems in accordance with LifePort, Inc., Master Drawing List EGR-549-00, Revision D, dated May 12, 2000, or later FAA approved revision.

NOTE: This installation includes provisions for mounting equipment in the cabin interior (via equipment sleds, arches and cabinets). Equipment mounted on these provisions, which is not specified in the above drawing package, requires separate FAA approval.

Limitations and Conditions: The additional installation of the LifePort Serviplex Unit in accordance with STC ST00365SE is required, as this STC provides the power and systems provisions. A maximum of one Serviplex Unit may be installed on the right side of the fuselage forward of the emergency exit. This STC provides an acceptable power source to activate the power and systems outlets on the Seriplex Unit. If this STC and STC ST00365SE are installed, the STC SA00120SE installation is not required. A copy of this Certificate and FAA approved LifePort Airplane Flight Manual Supplement, EGR-549-11, Revision IR, dated May 15, 2000, or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the

Federal Aviation Administration.

Date of application: March 6, 1998

Date reissued:

Date of issuance: May 15, 2000

Date amended:



By direction of the Administrator

[Handwritten Signature]

(Signature)

Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.