

Supplemental Type Certificate

Number SA02205SE

This certificate, issued to: **Cascade Flying Service LLC
903 Grinnell Road
Garfield, WA 99130**

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part ** of the ** Regulations.*

Original Product—Type Certificate Number: * *See attached Approved Model List (AML)
Make: SA02205SE for a list of
Model: approved aircraft models

Description of the Type Design Change: Installation of a replacement airframe fuel pump in accordance with Cascade Flying Service Master Drawing List FW-CFS545-90, Rev. B, dated October 19, 2011, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. This installation must be maintained in accordance with Cascade Flying Service document FW-CFS545-13, Rev IR, dated December 1, 2011, or later FAA approved revision.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 3, 2010 *Date reissued:*
Date of issuance: December 2, 2011 *Date amended:*



By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.