

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SH5257NM

This certificate, issued to Paravion Technology, Inc.

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product — Type Certificate Number: 4H12
Make: Schweizer
Model: 269B, 269C

Description of Type Design Change:

Installation of a Cockpit Mount Stand for provisions to mount a video monitor per Paravion Technology, Inc. Drawing List, Report No. DL-269MM, Rev. N/C, dated June 16, 1992, FAA approved July 20, 1992, or later FAA approved revision.

Limitations and Conditions:

1. This approval is for the mount only. The monitor must be separately FAA approved as noted in the installation instructions report PR-206MM-900M.
2. FAA Approved Rotocraft Flight Manual Supplement 269MM-100 dated July 21, 1992, or later FAA approved revision is required.
(See Continuation Sheet, Page 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 27, 1992

Date reissued:

Date of issuance: July 21, 1992

Date amended:



By direction of the Administrator

Richard E. Jennings
RICHARD E. JENNINGS (Signature) Supervisor
Denver Aircraft Certification Field Office
Northwest Mountain Region, Denver, Colorado

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

United States of America
Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number SH5257NM

3. Paravion Technology, Inc. Report No. PR-269MM-900M, "Monitor Mount Installation Instructions" dated July 14, 1992, or later revision is a required part of this installation.

4. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft.

5. A copy of this Certificate, Continuation Sheet, and FAA Rotocraft Flight Manual Supplement 269MM-100 dated July 21, 1992, or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

---E N D---

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.