

Supplemental Type Certificate

Number SA02146LA

This Certificate issued to LifePort, Inc.
1610 Heritage Street
Woodland, Washington 98674

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet A37CE.*

Original Product Type Certificate Number: A37CE

Make: Cessna

Model: 208, 208A, and 208B

Description Of Type Design Change: Installation of a Ballistic Protection System (BPS) in accordance with FAA Approved Master Drawing List for the Ballistic Protection System Installation in the Cessna Caravan 208 Series Aircraft, MDL-840-00, Revision B, dated May 22, 2008 or later FAA approved revision. FAA Approved Airplane Flight Manual Supplement No. EGR-840-11, dated May 28, 2008, or later FAA approved revision is required as part of this installation.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 16, 2008

Date reissued:

Date of issuance: June 2, 2008

Date amended:



By direction of the Administrator

Original signed by Gregory S. DiLibero

(Signature)

Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.