

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number ST02151NY

This certificate issued to Wilkerson Co., Inc.
PO Box 438
206 West Virginia Avenue
Crewe, VA 23930

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A21EA
Make: Bombardier, Inc.
Model: CL-600-2C10, CL-600-2D24, CL-600-2D15

Description of Type Design Change:

Installation of Dunlop Aircraft Tyres Limited Main Landing Gear Tyre(s) P/N DR32118T and Nose Landing Gear Tyre(s) P/N DR32212T in accordance with Aero Consulting Services Ltd. (ACS) Modification Data Summary Report No. D880000 Rev. B, dated December 21, 2006.

Limitations and Conditions:

1. Intermixing different nose landing gear part number tires on the same axle is not allowed.
2. For Continued Airworthiness, existing Aircraft Maintenance Manual (AMM) CSP B-001 and Dunlop Aircraft Tyres Limited Document DM1172, Entitled "General Servicing Instructions Aircraft Tyres and Tubes" are applicable for this installation.
3. The pressure maintenance of tires must be conducted in accordance with the intervals specified in Dunlop Document DM1172.
4. The Installer must determine whether this design change is compatible with previously approved modifications.
5. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 8, 2005

Date reissued:

Date of issuance: August 23, 2005

Date amended: April 17, 2007, January 30, 2008



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.