

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA09909SC

This certificate issued to:

Hawker Beechcraft Corporation
9709 E. Central
Wichita, KS 67206

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations. **
Certification basis is set forth in Type Certificate Data Sheet.

Original Product - Type Certificate Number: 3A20

Make: Raytheon (Beech)

Model: C90A

Description of Type Design Change: Installation of a 110 VAC Inverter with two (2) 110 VAC outlets in the cabin. Modifications in accordance with the FAA approved Master Data List, RAS25-340144D-MDL, Revision IR dated October 3, 2001, or later FAA approved revision. Airplane Flight Manual Supplement RAS25-340141D-AFMS, Revision IR dated October 7, 2001, or later FAA approved revision is required.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. The approval of this modification applies to the above noted airplane model series only. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 23, 2001

Date reissued: March 26, 2007

Date of issuance: October 15, 2001

Date amended:



By direction of the Administrator

Original signed by Charles Riddle

(Signature)

Charles D. Riddle
Program Manager
Wichita Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.