

Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA416NW

This certificate, issued to JOBMASTER COMPANY, INC.

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 10 of the Civil Air Regulations, Equivalent to CAR 3, Effective November 13, 1945.

Original Product — Type Certificate Number: A-806

Make: DeHavilland

Model: DHC-2 Mk I

Description of Type Design Change: Installation of EDO Model 61-5870 floats in accordance with Jobmaster Company Type Drawing J-77-2.

NOTE: This modification requires the installation of the following ventral fins or auxilliary vertical stabilizer:

Ventral Fin (Standard) - DeHavilland Drawing No. C2VF2557A

Ventral Fin (Large) - Jobmaster Company Drawing No. J74-18A

Auxilliary Vertical Stabilizer Fin - Jobmaster Company Drawing No. J-76-118

Limitations and Conditions: Approval is limited to the installation in the DeHavilland Model DHC-2 Mk I only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Jobmaster Flight Manual Supplement shall be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 10, 1977

Date reissued:

Date of issuance: March 10, 1977

Date amended:



By direction of the Administrator
Charles C. Schroeder
 (Signature)

Chief, Engineering and Manufacturing Branch
 (Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.