

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
IMPORT

Number **SR02232NY**

This certificate issued to

Heli-Lynx Helicopter Services Inc.
Stoney Creek Airport
684 Mud Street E, Hangar 1
Stoney Creek, Ontario
Canada L8J 3C9

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number:

H11EU

Make:

Eurocopter France

Model:

AS355E, AS355F, AS355F1, AS355F2

Description of Type Design Change:

Installation of Purolator De-Icing Fuel Filter P/N 1743640-01.

Limitations and Conditions:

1. Installation must be in accordance with Heli-Lynx Helicopter Services Master Drawing List MDL-PA-04-012-91-01 Issue 1, Rev. A, Transport Canada approved September 3, 2005, and Installation Manual Report No. IM-PA-04-012-91-01 Issue 2, Rev. A, Transport Canada approved September 3, 2005, or later Transport Canada approved revisions.

(See Continuation Sheet 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 25, 2005

Date reissued:

Date of issuance: February 01, 2006

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Supplemental Type Certificate

(Continuation Sheet)

Number **SR02232NY**

Date of Issuance: February 01, 2006

Limitations and Conditions (Continued):

2. Operation must be in accordance with Heli-Lynx Helicopter Services Flight Manual Supplement Report No. FMS-PA-04-012-91-01 Issue 2, Rev. Original, Transport Canada approved September 9, 2005, or later Transport Canada approved revisions.
3. Maintenance must be in accordance with Heli-Lynx Helicopter Services Maintenance Manual Supplement Report No. ICA-PA-04-012-05-01 Issue 2, Rev. B, Transport Canada accepted September 9, 2005, or later Transport Canada accepted revisions.
4. Compatibility of this design change with previously approved modifications must be determined by the installer.
5. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

...END...