

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02536NY

This certificate issued to Aero Consulting Services Ltd.
25 Dunlop Avenue
Winnipeg, Manitoba
Canada R2X 2V2

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A10CE

Make: Learjet

Model: 55

Description of Type Design Change:

The installation of Universal Avionics UNS-1C Flight Management System in accordance with Aero Consulting Services Modification Data Summary F335000 Revision N/C, dated September 07, 2007, or later Transport Canada approved revision.

Limitations and Conditions:

1. Operation must be in accordance with Aero Consulting Services Ltd. Airplane Flight Manual Supplement F335091, Transport Canada approved revision dated September 07, 2007, or later Transport Canada approved revision.
2. Maintenance must be in accordance with Mandatory Maintenance Manual Supplement, Report F335070, Revision N/C, Transport Canada approved revision dated August 29, 2007, or later Transport Canada approved revision and Bombardier Maintenance Requirements – Instructions for Continued Airworthiness, Document No. BAS55050014, Revision B, dated May 28, 2008, or later Transport Canada approved revision.
3. You cannot use descriptive data about this design change to duplicate other products. This approval is limited to only the installation made in Learjet 55, Serial Number 55-118. This STC does not permit manufacturing of parts for multiple installations.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 14, 2007

Date reissued:

Date of issuance: June 09, 2008

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.