

Supplemental Type Certificate

Number SA01446SE

This certificate, issued to **Aero Mark Inc.**
1940 International Way
Idaho Falls, Idaho 83402

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Civil Air Regulations.

Original Product—Type Certificate Number: A22NM
Make: Sky International (Aviat) Husky
Model: A-1, A-1A, and A-1B

Description of the Type Design Change: Installation of Hartzell HC-C2YR-1BF/F8477-4 propeller in accordance with Gate 9 Aircraft Maintenance, Inc. Document G9-II-PROP, Rev. N/C "Gate 9 Husky Propeller installation Instructions," dated March 11, 2004.

Limitations and Conditions: Approval of this change in type design applies to the above aircraft only. This approval should not be extended to other aircraft on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft.

This airplane must be maintained in accordance with document G9-II-PROP, Rev. N/C.

A copy of this Certificate and the Aircraft Flight Manual Supplement G9-AFMS-01, Rev. N/C, dated August 31, 2004 or later FAA approved revision of these documents, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 10, 2004 *Date reissued:* November 4, 2004
Date of issuance: August 31, 2004 *Date amended:* November 4, 2004



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.