

## Supplemental Type Certificate

*Number* SA01792SE

*This certificate, issued to* **Hartzell Propeller Inc.  
One Propeller Place  
Piqua, Ohio 45356-2634**

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.*

*Original Product—Type Certificate Number:* 6A1  
*Make:* Twin Commander  
*Model:* 500

*Description of the Type Design Change:* Installation of the Hartzell HC-C3YR-2UF/FC8468(A)(B,K)-6R propeller and the Hartzell C-3258 (P) spinner assembly in the above model aircraft in accordance with Hartzell Installation Report AC500, Rev. N/C, dated July 1, 2007, or later FAA-approved revision to this document.

*Limitations and Conditions:* Approval of this change in type design applies to the above model only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationships between this change and any of those other previously approved modifications including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this certificate shall be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, rendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* July 6, 2007

*Date reissued:*

*Date of issuance:* September 25, 2007

*Date amended:*



*By direction of the Administrator*

(Signature)

Acting Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.