

Supplemental Type Certificate

Number SA01402SE

This certificate, issued to:

**Cascade Flying Service LLC
903 Grinnell Road
Garfield, WA 99130**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21.25 of the Federal Aviation Regulations.

Original Product—Type Certificate Number:

** See FAA Approved Model List (AML)

Make:

No. SA01402SE for list of approved airplane

Model:

models and applicable airworthiness regulations.

Description of the Type Design Change: Install modified engine cowl per Cascade Aircraft Conversions LLC data given in AML SA01402SE for the specific model of airplane.

Limitations and Conditions: The modified aircraft must be maintained in accordance with Cascade Aircraft Conversions LLC data given in AML SA01402SE for the specific model of airplane.

Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 18, 2004

Date reissued:

Date of issuance: April 30, 2004

Date amended: October 27, 2004, May 9, 2007



By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.