

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number SA02449NY

This certificate issued to Marinvent Corporation
50, chemin de la Rabastalière Est, Suite 23
St-Bruno, QC Canada J3V 2A5

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A59EU
Make: PIAGGIO AERO INDUSTRIES S.p.A
Model: P-180

Description of Type Design Change:

The installation of Honeywell Epic Control Display System to be done in accordance with Avionics Design Services Ltd. Master Drawing List MDL05123, Revision B, dated April 5, 2007, or later Transport Canada approved revision.

Limitations and Conditions:

1. Operation must be in accordance with Marinvent Corporation Flight Manual Supplement FMS05123-1, Revision A, Transport Canada approved April 5, 2007, or later Transport Canada approved revision.
2. Maintenance must be in accordance with Avionics Design Services Ltd. Instructions for Continued Airworthiness ICA05123-1, Revision A, Transport Canada accepted April 5, 2007, or later Transport Canada accepted revision.
3. Basis of certification as defined in TCDS A59EU, Revision 15, plus FAR 23.1322, 23.1331 at amendment 23-43 and FAR 23.867, 23.1321, 1353(h) at amendment 23-49.
4. Equivalent safety findings exists with respect to the following regulation: 23.1545 (b)(4) Airspeed Indicator. RVSM operation not affected by this design change.

(See Continuation Sheet 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 14, 2006

Date reissued:

Date of issuance: August 23, 2007

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number SA02449NY

Date of Issuance: August 23, 2007

Limitations and Conditions (Continued).

5. A placard reading "MAXIMUM FLAP DN OPERATING SPEED: 150 KIAS" must be installed on the right side of the center console adjacent to the flap lever.
6. The installer must determine whether this design change is compatible with previously approved modifications.
7. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

.....END.....