

Supplemental Type Certificate

Number ST01335LA

This Certificate issued to C&D Zodiac, Inc.
5701 Bolsa Avenue
Huntington Beach, California 92647

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

Original Product Type Certificate Number: A16WE

Make: Boeing

Model: 737*

*See attached FAA Approved Model List (AML) No.
ST01335LA

Description of Type Design Change: Installation of a reinforced cockpit door in accordance with FAA approved C&D Interiors Controlled Drawing List, B221000, Revision B, dated June 26, 2002, or later FAA approved revisions.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. This STC is limited to Airplane Serial numbers specified on C & D Interiors Controlled Drawing List, B221000, Revision B, dated June 26, 2002, or later FAA approved revision. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

(Limitations and Conditions continued on page 3 of 3)

This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 4, 2002

Date reissued: Oct. 10, 2002; Jan. 30, 2006

Date of issuance: July 3, 2002

Date amended:

By direction of the Administrator



(Signature)

Manager, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office

(Title)

Supplemental Type Certificate

(Continuation Sheet)

Number ST01335LA

- The “demand access” time delay is certified from 30 to 60 seconds. Programming outside of the 30 to 60 second window would cause the aircraft to not be in a typed certificated configuration and therefore ineligible for an airworthiness certificate.
- If the “doorbell mode” of the electronic access system is enabled, any use of a “demand access” door access code must result in an immediate continuous aural alert. Programming any aural other than continuous aural alert would cause the aircraft to not be in a type certificated configuration and therefore ineligible for an airworthiness certificate.
- Equipment Functional Check Intervals as defined in FAA approved C & D Interiors Report CDRB22-69, Revision A, dated June 27, 2002, “Certification Maintenance Requirements,” or any later FAA approved revision, shall not be extended. Later revisions to C & D Aerospace Report CDRB22-69 may be used only if approved by the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office.
- If the holder agrees to permit another person to use the certificate to alter the product, the holder shall give the other person written evidence of that permission.

-----END-----