

Supplemental Type Certificate

Number **SR01279SE**

This certificate issued to

**Helicopter Transport Services, LLC
14497 Keil Road NE
Aurora, OR 97002**

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: H14NM
Make: Helicopter Transport Services
Model: CH-54B

Description of the Type Design Change: Installation of the Aero-Craft Utility Hydraulic Pump, Part Number (P/N) AP6VSPL in accordance with Helicopter Transport Services, Inc. (HTSI) Master Drawing List Document Number HTS-UHPMDL-001, Revision I/R, dated October, 16, 2002, or later Federal Aviation Administration (FAA) approved revision. This modification must be maintained in accordance with the maintenance instructions for the original Stratopower pump, P/N 65WK06001. No additional continued airworthiness instructions are required.

Limitations and Conditions: Approval of this change in type design applies to the HTSI Model CH-54B rotorcraft only. Rotorcraft modified by this supplemental type certificate must be operated in accordance with the Rotorcraft Flight Manual Supplement (RFMS) HTS-UHPFMS-54B-001, Revision -, FAA approved January 27, 2005, or later FAA-approved revision. A copy of this certificate, the maintenance instructions, and the RFMS must be maintained as part of the permanent records for the modified rotorcraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permissions.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 16, 2002

Date reissued: January 9, 2014

Date of issuance: October 8, 2003

Date amended: January 27, 2005



By direction of the Administrator

(Signature)

Manager, Seattle Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

