

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA00591DE

*This certificate issued to:*

**Gogo Business Aviation LLC  
105 Edgeview Drive Suite 300  
Broomfield, Colorado, 80021**

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23\* of the Federal Aviation Regulations. \*Certification basis established in Type Certificate Data Sheet applicable to 3A16.*

*Original Product - Type Certificate Number:* 3A16  
*Make:* Beech  
*Model:* 95-B55, Baron

*Description of Type Design Change:*

Installation of AirCell, Inc. ST 2100 ASE System in accordance with AirCell, Inc. Master Drawing List, Document No. 680-11396-000, Revision A, dated August 19, 2005, FAA approved dated October 19, 2005, or later FAA approved revision.

*Limitations and Conditions:*

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. Copy of this Certificate must be maintained as part of the permanent records for the modified aircraft.
3. Instructions for Continued Airworthiness: Document Number 820-11396-001, Revision D, dated October 14, 2005 or later FAA accepted revision is required for this installation.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* July 21, 2005

*Date reissued:* December 1, 2008; December 5, 2014

*Date of issuance:* October 19, 2005

*Date amended:*

*By direction of the Administrator*



(Signature)

Todd Dixon, Manager  
Northwest Mountain Region  
Denver Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.