

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02275NY

This certificate issued to Bombardier Inc.
200 Cote Vertu Road West
Dorval, Quebec
Canada H4S 2A3

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number : T00003NY
Make : Bombardier Aerospace
Model : BD-700-1A10, BD-700-1A11

Description of Type Design Change:

The installation of Heads-Up Technologies Checklist Management System CMS-400 to be done in accordance with Aero Consulting Services Modification Data Summary E938000, Revision A, dated May 23, 2006, or later Transport Canada approved revision.

Limitations and Conditions :

1. Operation must be in accordance with Aircraft Flight Manual Supplement, Document No. G-FM31404001, Transport Canada approved dated May 23, 2006, or later Transport Canada approved revision.
2. Maintenance must be in accordance with Maintenance Manual Supplement, Document No. G-TM31404001, Revision A, dated April 24, 2006, or later Transport Canada accepted revision.
3. Compatibility of this design change with previously approved modifications must be determined by the installer.
4. If the holder agrees to permit another person to use the certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : May 30, 2006

Date reissued :

Date of issuance : July 11, 2006

Date amended :



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.