

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR02315NY

This certificate issued to Agusta Aerospace Corporation
3050 Red Lion Road
Philadelphia, PA 19114

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H7EU
Make: Agusta
Model: A119

Description of Type Design Change:
Installation of a Shadin fuel flow meter.

Limitations and Conditions:

1. Installation is to be in accordance with Agusta Aerospace installation instructions report number AAC-ENG-06-002, Rev. -, and Agusta Master Document List (MDL) AAC-ENG-06-001, Rev. A, dated November 15, 2006.
2. Operation must be in accordance with Agusta Aerospace Rotorcraft Flight Manual Supplement Report No. AAC-ENG-06-006, Rev. -, dated November 28, 2006.
3. Maintenance is to be conducted in accordance with Agusta Aerospace Instructions for Continued Airworthiness report number AAC-ENG-06-007, Rev. -, dated August 14, 2006.
4. Compatibility of this design change with previously approved modifications must be determined by the installer.
5. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 20, 2006

Date reissued: November 5, 2007

Date of issuance: November 15, 2006

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.