

United States of America  
Department of Transportation -- Federal Aviation Administration

# Supplemental Type Certificate

IMPORT

*Number* ST02750NY

*This certificate issued to* ACS-NAI Limited  
25 Dunlop Avenue  
Winnipeg, Manitoba  
Canada R2X 2V2

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number:* T00003NY  
*Make:* Bombardier, Inc.  
*Model:* BD-700-1A10

*Description of Type Design Change:*

Modification to be completed in accordance with ACS-NAI Modification Summary G380000 Revision A dated September 2, 2009 or later Transport Canada approved revision.

*Limitations and Conditions:*

1. Refer to Aero Consulting Services Ltd. Airplane Flight Manual Supplement G380090 Revision N/C dated August 31, 2009 or later Transport Canada approved revision.
2. For Instructions for Continued Airworthiness refer to the Savannah Air Center Instructions for Continued Airworthiness for the installation of two 16G Side Facing Divans G380075 revision NC or later Transport Canada accepted revision.
3. Descriptive data pertaining to this design change are considered inadequate for duplication in other products. This approval is limited to only the installation made in Bombardier BD-700-1A10, Serial Number 9299. This STC does not permit manufacturing of parts for multiple installations.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* September 11, 2009

*Date reissued:*

*Date of issuance:* December 9, 2009

*Date amended:*

*By direction of the Administrator*



(Signature)

Anthony Socias  
Manager  
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.