

United States of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number **SA01538SE**

This certificate, issued to

**Dynamic Propeller LLC
341 Lisa Lane
Pasco, WA 99301**

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product—Type Certificate Number:

* See attached Federal Aviation Administration (FAA)

Make:

Approved Model List (AML) SA01538SE for approved

Model:

aircraft models and applicable airworthiness regulations

Description of the Type Design Change: Incorporation of bushing on carburetor hot air box control arm in accordance with Dynamic Propeller Installation Instructions No. 7000, Revision A, dated February 24, 2005, or later FAA-approved revision.

Limitations and Conditions: Approval of this change in type design applies to the aircraft models listed on AML SA01538SE only. This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined by the installer that the relationship between this change and any of those other previously approved modifications, will produce no adverse effect upon the airworthiness of that aircraft. A copy of this certificate must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 24, 2005

Date reissued: December 10, 2014

Date of issuance: April 27, 2005

Date amended:



By direction of the Administrator

(Signature)

Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.