

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SH3110SO

This certificate issued to

Bell Helicopter Textron, Inc.
441 Industrial Park Road
Piney Flats, TN 37686

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product -- Type Certificate Number: H2SW
Make: Bell Helicopter Textron Canada Limited
Model: 206A, 206B, 206L, 206L-1, 206L-3, 206L-4

Description of Type Design Change:

Installation of Composite Baggage Door in accordance with Aeronautical Accessories, Inc. Installation Instructions, Report No. AA-91062, Rev. A, dated December 30, 1991, and Drawing No. 206-502, Rev. A, dated December 23, 1991, or later FAA approved revisions.

Limitations and Conditions:

The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 8, 1991

Date reissued: November 26, 2012

Date of issuance: January 17, 1992

Date amended: October 5, 1992



By direction of the Administrator

(Signature)
Scott A. Horn, Acting Manager,
Rotorcraft Certification Office,
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.