

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number ST01137LA

This Certificate issued to Standard Aero
1200 North Airport Drive
Springfield, IL 62707

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal*

Original Product Type Certificate Number: T00003NY

Make: Bombardier

Model: BD-700-1A10, Global Express, Serial Number 9042 only

Aviation Regulations. Certification basis is set forth in Type Certificate Data Sheet.

Description of Type Design Change: Installation of Executive Cabin Interior in accordance with FAA Approved Jet Center Master Data List: Installation of an Executive Cabin Interior in Bombardier BD700-1A10 S/N 9042, document No. 210000001, revision No. "G", dated February 22, 1001, or later FAA approved revision. FAA Approved Airplane Flight Manual Supplements, Document No. 218654001, Revision "Original", dated, February 16, 2001, 218157001, revision "Original", dated February 16, 2001, and 218060001, Revision "Original", dated February 16, 2001, or later FAA approved revision.

Limitations and Conditions: This approval is limited to the installation made in the model airplane Serial No. 9042 only. The maximum number of passengers is fourteen (14) based on the number of seats approved (14 CFR 25.562) for Taxi, Takeoff, and Landing. Installation of the following STCs are required as part of this modification: SA8166NM-D – Installation of a Securaplane Emergency Lighting System; ST00941LA – Installation of Floor Proximity Emergency Escape Path Marking System.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered.

Date of application: June 14, 2000

Date reissued: July 30, 2003, February 27, 2014

Date of issuance: February 23, 2001

Date amended:

suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

By direction of the Administrator



(Signature)

Supervisor, Technical & Administrative
Support Staff, Los Angeles Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.