

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02512NY

This certificate issued to Bombardier Inc.
200 Chemin Cote Vertu Quest
Dorval, Quebec
Canada H4S 2A3

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: T00005NY

Make: Bombardier, Inc.

Model: BD-100-1A10

Description of Type Design Change:

AVS-470 Tail Camera System to be done in accordance with Aero Consulting Services Modification Data Summary, F161001, Revision N/C, dated May 2, 2007, Transport Canada approved August 3, 2007, or later Transport Canada approved revision.

Limitations and Conditions:

1. Maintenance must be in accordance with Bombardier Report - Instructions for Continued Airworthiness, Document RAL-BV100-5104-IFCA-1, Revision N/C, dated May 1, 2007.
2. The installer must determine whether this design change is compatible with previously approved modifications.
3. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 13, 2007

Date reissued:

Date of issuance: February 21, 2008

Date amended:

By direction of the Administrator



(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)