

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA8073SW

This Certificate issued to Honeywell International Inc.
dba Honeywell LORI
6930 North Lakewood
Tulsa, Oklahoma 74117-1804

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations..*

Original Product - Type Certificate Number: *See attached FAA Approved Model List (AML)
Make:
Model:

Description of Type Design Change:

Replace core assembly of AiResearch Reheater Heat Exchanger, Part Number 194274-3 and 194274-4 in accordance with LORI Drawing Number 88LB2110, Rev. D, dated June 8, 1993, or later FAA approved revision.

Limitations and Conditions:

Compatibility of this modifications with previously installed equipment is the responsibility of the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 8, 1990

Date reissued : 10/1/96; 11/15/05; 11/14/12

Date of issuance: July 8, 1991

Date amended: November 9, 1994 Rev. 1



By direction of the Administrator

(Signature)

William S. Shealy

ODA lead administrator

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.