

Supplemental Type Certificate

Number SA01087SE

This certificate, issued to

**Mr. Thomas R. Anderson
295 East Perimeter Road
Renton, WA 98057**

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

<i>Original Product—Type Certificate Number:</i>	* See attached Federal Aviation Administration (FAA)
<i>Make:</i>	Approved Model List (AML) SA01087SE for approved
<i>Model:</i>	aircraft models and applicable airworthiness regulations

Description of the Type Design Change: Installation of titanium main landing gear assembly in accordance with the applicable FAA-approved Master Drawing List as specified on AML SA01087SE.

Limitations and Conditions: Approval of this change in type design applies to the model aircraft as listed on AML SA01087SE only. This approval should not be extended to other aircraft on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this certificate and AML must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 19, 2001

Date reissued:

Date of issuance: May 14, 2002

Date amended: 3/21/03; 3/21/13; 8/28/14



By direction of the Administrator

(Signature)

Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

