

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number ST00797SE

This certificate, issued to

**Merlyn Products, Inc.
West 7500 Park Drive
Spokane, WA 99224**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4a of the Civil Aviation Regulations.

Original Product—Type Certificate Number: A743
Make: Boeing
Model: A75L3, 75, A75, B75, D75N1,
E75, A75J1, A75N1, B75N1

Description of the Type Design Change: Install landing gear strut seal assembly in accordance with Merlyn Products, Inc. Top Drawing List 75.8-TDL, Revision B, dated January 15, 2001, and Merlyn Products, Inc. Document 75.8-01, Revision B, dated January 15, 2001, titled "Installation Instructions," or later FAA approved revisions.

Limitations and Conditions: Eligibility for this modification is limited to the above model aircraft with Bendix main landing gear installed. This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined by the installer that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this Certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 22, 2000 *Date reissued:*
Date of issuance: May 3, 2000 *Date amended:* January 30, 2001



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.