

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SR00419DE

This certificate, issued to

**Air Comm Corporation
1575 West 124th Ave
Westminster, CO 80234**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Title 14, Part 27 of the Code of Federal Regulations

Original Product—Type Certificate Number: R00001RC

Make: Bell Helicopter Textron

Model: 427

Description of the Type Design Change:

Installation of Cabin Heater in accordance with Air Comm Corporation Master Drawing List Report No. DL-427H, revision C, dated March 9, 2000, FAA approved May 15, 2000, or later approved revision.

Limitations and Conditions:

1. FAA Approved Flight Manual Supplement, 427H-1, dated May 15, 2000 or later approved revision is required.
2. FAA Accepted Instructions for Continued Airworthiness, 427H-201M-1, revision 0, or later accepted revision is required.
3. Approval of this change in type design applies to the model of aircraft listed above only.
4. Compatibility of this design change with previously approved alterations must be determined by the installer.
5. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.
6. A copy of this certificate and the appropriate flight manual supplement as listed above must be maintained as part of the permanent record for the altered aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 4, 1998

Date reissued: November 24, 2014

Date of issuance: May 15, 2000

Date amended: 9/27/00, 11/13/00

By direction of the Administrator



Todd Dixon (Signature)
Manager Denver Aircraft Certification Office
Northwest Mountain Region.

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.