

FAA APPROVED MODEL LIST (AML) NO. **SR02243NY**

INSTALLATION OF BAGGAGE SMOKE DETECTOR REPLACEMENT

Re- issue Date: March 27, 2006

MAKE	MODEL	CERTIFICATION BASIS			REQUIRED DOCUMENTATION		AML AMENDMENT DATE
		PART	REGULATION	TCDS	MAINTENANCE MANUAL SUPPLEMENT	FLIGHT MANUAL SUPPLEMENT	
Bell	205B	CAR 7 FAR 29	Federal Aviation	H1SW	Instructions for Continuing Airworthiness Supplement Document AER-2004-MAINT-001, Rev. 03 dated February 10, 2006 or later TCCA accepted revisions	The DOT Approved Flight Manual Supplement for Baggage Smoke Detector Replacement document AER-FMS-013, Rev. 01, dated March 30, 2005, or later TCCA approved revision, is required as part of this installation.	
	212, 412, 412EP	FAR 29		H4SW	Instructions for Continuing Airworthiness Supplement document AER-2004-MAINT-001, Rev. 03 dated February 10, 2006 or later TCCA accepted revisions		
	222B, 222U, 230, 430	FAR 29		H9SW	Instructions for Continuing Airworthiness Supplement for AER-2005-MAINT-001, Rev. 03 dated February 22, 2006 or later TCCA accepted revisions.		

FAA Approved: _____

Anthony Socias
Manager, New York Aircraft Certification Office