

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA399CE

*This certificate issued to*

BF Goodrich Aerospace  
Lighting Systems Division  
3445 South 5<sup>th</sup> Street  
Phoenix, AZ 85040

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 10 of the Civil Air Regulations.*

*Original Product--Type Certificate Number:* A-807

*Make:* DeHavilland

*Model:* 104

*Description of Type Design Change:* Installation of Hoskins Supplemental Position Light System which includes Model B (Dual) Wing Tip Light, Model C, D, or K Tail Light with or without Model 2 Fuselage Lights.

**Data Required:** (1) General installation instructions as amended February 18, 1996 Hoskins Specification Sheets, 6 pages Dated February 18, 1966. (2) Hoskins drawings DH-104, Sheets 1 and 2: 30-0028 Sheets 1 & 2; 22-1-B or 30-0108; 30-0021 or 30-0022, Specifications Sheet P/N 65-0035-1 dated June 03, 1968.

*Limitations and Conditions:* **LIMITATION OF APPLICABILITY.** This approval should not be extended to other specific airplanes of these models on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those previously approved modifications will introduce no adverse effect upon the airworthiness of the airplane.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* September 19, 1962

*Date reissued:* October 17, 1974, April 1, 1990,  
September 25, 1995, January 31, 1996,  
September 30, 2011

*Date of issuance:* February 18, 1966



*Date amended:* June 26, 1968

*By direction of the Administrator*

(Signature)

Melvin D. Taylor  
Manager, Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.