

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number **SA00849WI**

This certificate issued to:

Hawker Beechcraft Corporation
9709 E. Central
Wichita, KS 67206

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product - Type Certificate Number: 3A15
Make: Beech
Model: 36; A36; A36TC; B36TC

Description of Type Design Change: Installation of a Dual Garmin GNS-430 Communications Transceiver / VOR/ILS Receiver / GPS Receiver, with Single Garmin GI-106A Course Deviation Indicator, Mid-Continent Instruments MD41-1468 GPS Annunciator, Ps Engineering PMA7000M-S Audio Panel, Shadin ADC-200 Fuel / Air Data Computer and BF Goodrich WX-500 Weather Mapping Sensor. Data Required: (1) Elliot Aviation Drawing List, Document No. 900185-001, Rev. 0, dated December 6, 1999; and (2) Elliott Aviation, Document No. 900185-002, Rev. 0, FAA Approved Airplane Flight Manual Supplement, dated February 9, 2000; or later FAA Approved Revisions to (1) or (2).

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 26, 1999

Date reissued: March 27, 2000; March 26, 2007

Date of issuance: February 9, 2000

Date amended:

By direction of the Administrator

Original signed by Charles Riddle

(Signature)

Charles D. Riddle
Program Manager
Wichita Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.