

# Supplemental Type Certificate

*Number* SA01078SE

*This certificate, issued to* **Aero Air, LLC  
2050 NE 25<sup>th</sup> Ave.  
Hillsboro, OR 97124**

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.*

*Original Product — Type Certificate Number:* 2A4  
*Make:* Twin Commander  
*Model:* 690, 690A, 690B

*Description of the Type Design Change:* Installation of externally mounted fuel pump manufactured in accordance with Master Drawing List AEA105-90, Revision A, dated April 5, 2002, or later FAA approved revision, and installed in accordance with Installation Instructions VT-AEA105-12, Revision IR, dated April 5, 2002, or later FAA approved revision. Maintain in accordance with Instructions for Continued Airworthiness AEA-105-13, Revision IR, dated April 5, 2002, or later FAA approved revision.

*Limitations and Conditions:* This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the relationship between this change and other previously approved modification will introduce no adverse effect upon the airworthiness of the aircraft. A copy of this Certificate must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* September 9, 1999      *Date reissued:*  
*Date of issuance:* April 17, 2002      *Date amended:*



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
Acting Manager, Seattle Aircraft  
Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

\_\_\_\_\_  
(Title)

*This certificate may be transferred in accordance with FAR 21.47.*