

# Supplemental Type Certificate

*Number* SA1993NM

*This Certificate issued to* ROBERT W. MURRAY  
24196 Zancon  
Mission Viejo, California 92692

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4b of the Civil Air Regulations.* as listed under certification basis of Supplemental Type Certificate (STC) SA1054WE

*Original Product Type Certificate Number :* A-793 (STC SA1054WE)

*Make :* General Dynamics/Convair

*Model :* 600 (240D)

*Description of Type Design Change:* Installation of a de-icing system on the Rolls Royce P/N RK45524A engine inlet cowl in accordance with Montgomery Systems Tech Drawings 465104, Revision N/C; 465105, Revision N/C; and 465106, Revision N/C, all dated November 28, 1982, or later FAA approved revision, as an alternate to the Dunlop deicing system currently approved.

*Limitations and Conditions:* This approval should not be extended to other specific airplanes of this model on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect on the airworthiness of those aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* November 23, 1982

*Date reissued :* August 31, 2006, December 20, 2011

*Date of issuance :* July 15, 1983

*Date amended :* August 31, 2006

*By direction of the Administrator*



(Signature)

Haifa Haj-Eid  
Supervisor, Technical and Administrative Support  
Staff

Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

NOTE:

DO NOT DELETE THIS PAGE.

DO NOT ADD ANY DATA TO THIS PAGE.

THIS PAGE IS FOR PAGE NUMBERING PURPOSES,  
PLEASE DISCARD PRINTED COPY.

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*