

# Supplemental Type Certificate

Number SH287NW

*This Certificate issued to* Siam Hiller Holdings, Inc.  
925 M Street  
Firebaugh, California 93622

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.* effective January 15, 1951. See page 3 of this STC for certification basis.

*Original Product Type Certificate Number:* 4H10

*Make:* Hiller

*Model:* UH-12D

*Description of Type Design Change:* Installation of Hiller landing gear float kit No. 44012 in accordance with FAA approved Soloy Drawing List 560-601.

**NOTE:** Only those Hiller UH-12D rotorcraft which have been converted to turbine power in accordance with STC SH177WE are eligible for this modification.

*Limitations and Conditions:* Approval of this change in type design applies to the above model rotorcraft only. This approval should not be extended to other rotorcraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that rotorcraft. A copy of this Certificate must be maintained as part of the permanent records for the modified rotorcraft. The limitations and conditions of Rotorcraft Type Certificate 4H10 and STC SH177WE apply except as outlined on page 3 of this STC. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* February 24, 1976

*Date reissued:* 06/02/83; 10/25/84; 05/28/91;  
11/30/95; 05/13/05

*Date of issuance:* April 23, 1976

*Date amended:* 05/28/91



*By direction of the Administrator*

(Signature)

Manager, Technical & Administrative Support  
Staff, Los Angeles Aircraft Certification Office  
(Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

United States Of America  
Department of Transportation - Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

SH287NW

*Limitations and Conditions:* (Continued)

The limitations and conditions described in STC SH177WE are applicable to this modification except as detailed below:

1. Air Limits                    44012 Floats - CAS  
Sea level to 2,000 ft.    86 mph  
12,000 ft.                    62 mph  
Straight-line variation between points given.
  
2. C.G. Range                44012 Floats  
Longitudings                (+81.0) to (+84.8)  
Lateral no change from SH177WE
  
3. Horizontal Stabilizer Rigging Minus 10° with 44012 floats installed and rotorcraft level.
  
4. Rotorcraft Flight Manual  
  
FAA approved Soloy Conversions, Ltd. Rotorcraft Flight Manual, dated April 10, 1975, with Supplement dated April 23, 1976, is required in lieu of that specified for the basic Model UH-12D. Refer to the applicable portions of this FAA approved Soloy Conversions, Ltd. Rotorcraft Flight Manual for the required placards and instrument markings.
  
5. Certification Basis
  - a. Civil Air Regulations Part 6 dated December 20, 1956, with Amendment 6-1 through 6-3 thereto.
  
  - b. The following paragraphs of Federal Aviation Regulations Part 27 including Amendment 27-1 thereto.  
  
27.45 through 27.79, 27.143, 27.361(a), 27.901 through 27.1193, 27.1305, 27.1337, 27.1351(c), 27.1353, 27.1505, 27.1509(c), 27.1521, 27.1549 through 27.1555, 27.1557, 27.1559, 27.1583(b), and (f), 27.1587, 27.1589.
  
  - c. Special Conditions 27-1-WE-1, dated August 6, 1968, and Amendment 1 thereto dated February 28, 1975.

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*