

# Supplemental Type Certificate

*Number* SA10392SC

*This certificate, issued to*

**Eagle Creek Aviation Services  
4101 Dandy Trail  
Indianapolis, IN 46254**

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations*

*Original Product—Type Certificate Number:*

2A4

*Make:*

Twin Commander Aircraft Corporation

*Model:*

690C; 690D; 695; 695A; 695B

*Description of the Type Design Change:* Installation of a dual Innovative Solutions & Support (IS&S) Altimeter System in accordance with Twin Commander Aircraft Company Master Drawing List No. 800822, Rev. B, dated March 17, 2005, or later FAA approved revision. FAA approved Airplane Flight Manual Supplement Document No. IS&S-1, Rev. IR, dated March 23, 2005, or later FAA approved revision is required.

*Limitations and Conditions:* Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

See Continuation Sheet – Page 3

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* April 5, 2004

*Date reissued:*

*Date of issuance:* March 31, 2005

*Date amended:*



*By direction of the Administrator*

\_\_\_\_ Original signed by Angelos Xidias \_\_\_\_\_

(Signature)

Acting Manager, Seattle Aircraft  
Certification Office

\_\_\_\_\_  
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

*This certificate may be transferred in accordance with FAR 21.47.*

UnitedStatesofAmerica  
DepartmentofTransportation\_FederalAviationAdministration  
**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* SA10392SC

**Eagle Creek Aviation Services**

Reissued: July 9, 2007

Amended:

*Special Conditions:* 23-161-SC

*Limitations and Conditions: (cont'd)*

Regulations at the latest amendments 23-0 through 23-55

23.29, 23.301, 23.303, 23.305, 23.307, 23.321, 23.331, 23.335, 23.337, 23.341, 23.365 (d), 23.571 (a), 23.601, 23.603, 23.605, 23.609, 23.611, 23.613, 23.771 (a), 23.867, 23.1301 (a, b, c, d), 23.1303 (a, b, c), 23.1307, 23.1309, 23.1321, 23.1322, 23.1325 (a, b), 23.1331, 23.1351 (a, b), 23.1353 (h), 23.1357 (a-d), 23.1359 (c), 23.1365 (a, b, d-f), 23.1367, 23.1381, 23.1431 (a, b), 23.1501, 23.1529, 23.1541 (a2), 23.1543, 23.1581, 23.1585 (a)(j).

- END -

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

---

FAA FORM 8110-2-1 (10-69)

*This certificate may be transferred in accordance with FAR 21.47.*