

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SR01449AT

*This certificate issued to*

Bell Helicopter Textron Inc.  
441 Industrial Park Road  
Piney Flats, TN 37686

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21.25 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number:* R00006DE; H22NM; R00002LA  
*Make:* Rotorcraft Development Corporation  
*Model:* OH-58A, OH-58A+, OH-58C

*Description of Type Design Change:*

Manufacture of replacement Transmission Cowling Doors in accordance with Aeronautical Accessories, Inc. Report No. AA-97079, no revision, dated June 5, 1997 or later FAA approved revisions and installation per Report No. AA-96063, Revision A, dated May 6, 1997, or later FAA approved revisions.

*Limitations and Conditions:*

The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* April 18, 1997

*Date reissued:* July 25, 2011

*Date of issuance:* August 14, 1997

*Date amended:* September 24, 1997;  
August 06, 1999



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
James A. Richmond, Acting Manager,  
Rotorcraft Certification Office,  
Southwest Region

\_\_\_\_\_  
(Title)

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*