

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SH26RM

This certificate, issued to Parker Hannifin Corporation
Airborne Division (Formerly JB Systems)
P.O. Box 800
Longmont, Colorado 80501

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21.19 & 27 of the Federal Aviation Regulations.

Original Product — Type Certificate Number: H3EU
Make: Messerschmitt-Bolkow-Blohm
Model: BO-105A and BO-105C

Description of Type Design Change:

Installation of Freon Airconditioning System. DATA REQUIRED: FAA Sealed Drawing List No. 45-001, dated February 28, 1974, and FAA Approved Aircraft Flight Manual Supplement for air conditioning to Helicopter Model No. BO-105A and BO-105C dated June 14, 1974, or subsequent FAA Approved revisions.

Limitations and Conditions: This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. Except for helicopter Serial Number S104, parts manufactured and installed under this STC must be approved and marked in accordance with the requirements of FAR 21.303 and FAR 45.15.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 28, 1974

Date issued: July 21, 1981

Date of issuance: June 14, 1974

Date amended:



By direction of the Administrator

Mark E. Baldwin
MARK E. BALDWIN, (Signature)
Engineering and Manufacturing Branch
Rocky Mountain Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.