

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
**IMPORT**

*Number* **ST02134NY**

*This certificate issued to*

Transwest Helicopters Ltd.  
46185 Olds Drive  
Chilliwack, British Columbia  
V2P 6H7, Canada

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number:* H6SW

*Make:* Bell

*Model:* 214B, 214B-1

*Description of Type Design Change:*

The installation of a Concorde RG0380 Sealed Lead Acid Battery to be done in accordance with Transwest Helicopters Ltd. Engineering order 241-EO-001 Revision 0, dated October 6, 2004. Transport Canada approved November 17, 2004, or later Transport Canada approved revision.

*Limitations and Conditions:*

1. Maintenance must be in accordance with Transwest Helicopters Ltd. ICA Report Number 241-ICA-001, Revision 1R, dated June 15, 2005 or later FAA Accepted revision.
2. Operation must be in accordance with Transwest Helicopters Ltd. Flight Manual Supplement, 241-FMS-001, Revision 0, dated October 7, 2004, Transport Canada approved November 17, 2004 or later Transport Canada approved revision.
3. Compatibility of this design change with previously approved modifications must be determined by the installer.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* November 29, 2004

*Date reissued :*

*Date of issuance :* June 28, 2005

*Date amended :*



*By direction of the Administrator*

(Signature)

Michele J. Maurer  
Acting Manager,  
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.