

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
IMPORT

Number SR02774NY

This certificate issued to
VIH Aerospace
1962 Casno Road
North Saanich, BC
Canada V8L 5V5

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H88EU

Manufacturer: Eurocopter Deutschland GmbH

Model: EC 135

Description of Type Design Change:

Installation of RHS Bubble Window in accordance with VIH Aerospace Master Drawing List V135-0811-MDL Revision 0, dated July 18, 2008, Transport Canada approved November 17, 2009 or later Transport Canada approved revision

Limitations and Conditions:

1. VIH Aerospace ICA No. V135-0811-ICA Revision 1 dated September 11, 2009, Transport Canada accepted on November 19, 2009, or later Transport Canada accepted revision is required with this STC.
2. Operation must be in accordance with VIH Aerospace Flight Manual Supplement V135-0811-FMS Revision 1 dated May 7, 2009, Transport Canada approved November 19, 2009 or later Transport Canada approved revision.
3. The Installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: December 21, 2009

Date reissued: April 28, 2010

Date of issuance: March 15, 2010

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.