

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number ST01787NY-D

This certificate issued to Dassault Falcon Jet- Wilmington Corp.
191 North DuPont Highway
New Castle, DE 19720

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number : A46EU
Make : Dassault Aviation
Model : Mystere Falcon 900

Description of Type Design Change : Installation of Triple Honeywell Aerospace Electronics PRIMUS 2000 Flight Management System software version NZ 6.0 Upgrade in accordance with Dassault Falcon Jet-Wilmington Master Drawing List, 147450300, Revision -, dated October 18, 2005.

Limitations and Conditions :

- (1) Airplane Flight Manual Supplement 147450303, Revision -, FAA approved Oct 24, 2005 is required with this installation.

(See Continuation Sheet Page 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 26, 2005

Date reissued: -

Date of issuance : October 24, 2005

Date amended: -



By direction of the Administrator

(Signature)
Joseph Licata

Administrator, DAS-955240-NE

(Title)

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number ST01787NY-D (Continued)

Date of Issuance: Oct 24, 2005

Date Amended :

Limitations and Conditions (continued)

- (2) Instructions for Continued Airworthiness (ICA) 147450306, Revision -, dated October 18, 2005 is required with this installation.
- (3) This design change is applicable to Dassault Aviation Mystere Falcon 900 aircraft which have previously been equipped with Honeywell Avionics Primus 2000 Flight Management System (FMS), software version NZ5.1() or NZ5.2(), in accordance with the following:
- a. Dassault Aviation Service Bulletin 328 (Dassault Aviation Mods M3322, M3624, M3512, M3333)
 - or
 - b. Dassault Aviation Service Bulletin 332 (Dassault Aviation Mods M2689, M3624, M3512, M3333)
 - or
 - c. Dassault Aviation Service Bulletin 339 (Dassault Aviation Mod M3813)
 - or
 - d. Dassault Aviation Service Bulletin 349 (Dassault Aviation Mod M3827)
 - or
 - e. Dassault Aviation Modification M3206
 - or
 - f. Dassault Aviation Modification M1975, M2695, M3206, M3064
- (4) Compatibility of this design change with previously approved modifications must be determined by the installer
- (5) If the holder of this certificate permits another person to incorporate the modifications, the holder will give person written evidence of this permission.

.....END.....