

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA2091WE

This certificate issued to

ACC-KP, LLC
4554 Claire Chennault St.
Addison, TX 75001

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product -- Type Certificate Number:

A7CE

Make:

Cessna

Model:

401 & 401A all S/N's; 402, 402A & 402B thru
S/N 0300; 411 & 411A all S/N's; 414 thru
S/N 0350; 421, 421A & 421B thru S/N 0300

Description of Type Design Change:

Installation of air-conditioning system in accordance with Drawing List 40-001 dated January 20, 1970, or DL-40-001 dated May 18, 1979, or subsequent FAA approved revisions.

Limitations and Conditions:

(See continuation sheet 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 6, 1969

Date reissued: 10/7/85; 3/23/90;
8/14/92; 9/14/10; 5/17/13

Date of issuance: January 20, 1970

Date amended: 9/1/70, 2/5/71, 5/21/79,
1/22/80, 2/4/81 Rev. 5



By direction of the Administrator

(Signature)

S. Frances Cox, Manager,
Special Certification Office,
Southwest Region

(Title)

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number SA2091WE

Date of Issuance: January 20, 1970

Reissuance Date: May 17, 2013

Limitations and Conditions (Continued):

1. Installation is limited to airplanes having 100 amp alternators.
2. FAA Approved Airplane Flight Manual Supplement dated February 5, 1971, or subsequent FAA approved revision is required with this modification.
3. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

-END-