

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SS01719AT

Reissued on December 10, 2012 to supersede the original STC which is lost, misplaced, or destroyed.

This certificate issued to Airship Management Services Inc.
31 Brookside Drive
Greenwich, CT 06830

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: AS1EU

Make: Skyship

Model: 600

Description of Type Design Change:

Installation of a gyroscopic turn and bank indicator and rearrangement of instruments in the "basic T" to meet the requirements for instrument flight rule (IFR) operations in accordance with Airship Management Services Master Document Index AMS 97/010, Rev B, dated April 1998, or later FAA approved revision.

Limitations and Conditions: FAA approved Airship Flight Manual Supplement No. AMS/1 dated October 5, 1998, or later FAA approved revision, is required. Compatibility of this design change with other previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 26, 1997

Date reissued: December 10, 2012
March 27, 2013

Date of issuance: October 5, 1998

Date amended:



By direction of the Administrator

(Signature)
Melvin D. Taylor, Manager
Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.