

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SA4835SW

This Certificate issued to Aero Safe Corporation,
a Texas Corporation
5300B Airport Road
Mineral Wells Municipal Airport
Mineral Wells, TX 76067

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product Type Certificate Number : 3A15

Make : Beech

Model : 36; A36; A36-TC; B36; B36-TC; E33A; F33;
F33A; G33; V35A; V35B; V35A-TC; V35B-TC

Description of Type Design Change:

Installation of an electrically driven air pump as a standby auxiliary pump to the existing instrument air system in accordance with Drawing List 820600, Revision C dated 9/30/83, or later FAA approved revision.

Limitations and Conditions:

Maximum operating altitude for auxiliary instrument air source system in 24,000 feet MSL. The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 15, 1982

Date reissued : 4/17/00; 4/6/07

Date of issuance : November 12, 1982

Date amended : 11/15/82; 5/4/83; 2/15/84;
10/18/84; 12/11/00 Revision 5



By direction of the Administrator

(Signature)

S. Frances Cox, Manager,
Special Certification Office,
Southwest Region

(Title)

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.