

DepartmentofTransportation_FederalAviationAdministration

Supplemental Type Certificate

Number SR01605SE*This certificate, issued to***Aerometals
3920 Sandstone Drive
EI Dorado Hills, CA 95762**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

<i>Original Product—Type Certificate Number:</i>	H3WE
<i>Make:</i>	MD Helicopter, Inc.
<i>Model:</i>	369D, 369E, 369FF, 369HE, 369HM, 369HS

Description of the Type Design Change: Fabrication of Aircraft Manufacturing Company (AMC) Part Number AM369H2039-501/-502 oil cooler access door assembly in accordance with AMC Master Drawing List No. MDL-AMC-021, Revision IR, dated March 25, 2005, or later Federal Aviation Administration (FAA) approved revision. The oil cooler door assembly must be installed in accordance with AMC Installation Instructions AMC MI-05003, Revision IR, dated March 17, 2005, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the rotorcraft models listed above only. This approval should not be extended to other rotorcraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effects upon the airworthiness of that rotorcraft. A copy of this Certificate must be maintained as part of the permanent record of the modified rotorcraft. This is a direct replacement part, and the FAA has determined that no Instructions for Continued Airworthiness are required.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 1, 2005*Date reissued:* June 28, 2006*Date of issuance:* September 30, 2005*Date amended:**By direction of the Administrator*

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.