

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number ST02559AK

This certificate issued to Aero Twin, Inc.
2403 Merrill Field Drive
Anchorage, Alaska 99501

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations

Original Product – Type Certificate Number: A43EU
Make: EADS CASA
Model: C-212-CB, -CC, -CD, -CE, -CF, -DF

Description of Type Design Change:

Installation of Aero Twin, Inc. CASA 212 Exhaust Deflector, part number AT-CASA-EXDF-1001 in accordance with Aero Twin, Inc. Master Data List No. AT-CASA-EXDF-MDL, Original Issue, dated June 22, 2010, or later FAA approved revision. This is an approximately 12” stainless steel exhaust deflector/extension that bolts to the existing engine exhaust using standard (high temperature) hardware for the purpose of reducing exhaust impingement and subsequent corrosion on the underside of the wing.

Limitations and Conditions:

1. Compatibility of the design change with previously approved modifications must be determined by the installer.
2. For Instructions for Continued Airworthiness, refer to Aero Twin, Inc. Doc. No. CASA-212-EXDF-ICA, Original Issue, dated June 25, 2010, or later FAA accepted revision.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 21, 2010
Date of issuance: September 10, 2010

Date reissued:
Date amended:



By direction of the Administrator

(Signature)

August A. Asay
Manager, Anchorage Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.