

Supplemental Type Certificate

(Continuation Sheet)

Number ST01563SE

Issued to: Flight Structures, Inc.

Date of Issuance: August 18, 2005

Date Amended:

Limitations and Conditions (cont'd):

Supplemental Type Certificate ST02221AT SAF-T-GLO Photoluminescent floor proximity emergency escape path marking system must be installed concurrently with this modification.

The Supplemental Instructions for Continued Airworthiness, Flight Structures Document A4FS410-D15, Revision IR, dated June 10, 2005 or later FAA accepted revision must be incorporated into the operator's maintenance program.

Airplane Flight Manual Supplement, Flight Structures Document TP4-410AFM, dated March 25, 2005 or later FAA approved revision is applicable to airplanes modified in accordance with this STC.

Certification Basis:

The certification basis for this modification is in accordance with Type Certificate Data Sheet A2NM, with the following exceptions:

Regulations at a later amendment than specified in A2NM:

14 CFR §§ 25.791(a)(b)(e)	Amendment 25-72
25.853(a)(c)(d)(e)(f)	Amendment 25-83
25.869(a)(1)(4)	Amendment 25-72
25.981(a)(b)	Amendment 25-102
25.1529	Amendment 25-54
25.1585	Amendment 25-105

----- **END** -----

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.