

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number ST02281AK

This Certificate issued to

Jet Midwest Group
5959 W. Century Boulevard, Suite 1412
Los Angeles, CA 90045

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product Type Certificate Number: A31SO
Make: Embraer
Model: EMB-120QC

Description of Type Design Change:

Installation of an increased security cockpit door, in accordance with Cascade Aviation, Inc., Master Drawing List 02CAS070-MDL, Revision B, dated February 17, 2003, or later FAA approved revision.

Limitations and Conditions:

- 1) Compatibility of this design change with previously approved modifications must be determined by the installer.
- 2) This installation approval is limited to Embraer Model EMB-120QC, Serial Number 120264.
- 3) An Equivalent Level of Safety Finding exists with respect to Title 14, Code of Federal Regulations (14 CFR) section 25.1309(c). (Reference FAA Equivalent Level of Safety Memorandum Number ST6910SE-T-S-1, Revision 2, dated November 21, 2006)
- 4) For instructions for continued airworthiness, refer to Cascade Aviation Services, Inc., "Instructions for Continued Airworthiness", Document No. 02CAS070-D30, Revision B, dated December 9, 2002.
- 5) Everts Air Cargo, Airplane Flight Manual Supplement, Document No. EAC 11-16-06-N462CA, dated January 10, 2007 or later FAA approved revision, is a required part of this modification.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 11, 2006

Date reissued: July 2, 2013

Date of issuance: January 10, 2007

Date amended:



By direction of the Administrator

(Signature)

August A. Asay
Manager, Anchorage Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.