

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SR01968NY-D

*This certificate issued to* Heli-One USA Inc.  
9000 Trinity Blvd.  
Hurst, TX 76053

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.*

*Original Product Type Certificate Number:* H13EU

*Make:* Eurocopter Deutschland GmbH

*Model:* MBB-BK 117 C-2

*Description of Type Design Change:*

Installation of medical interior in a Eurocopter MBB-BK 117 C-2 aircraft in accordance with Keystone Helicopter Installation Drawing List IDL01012 Rev. A dated 8/16/05 or later approved revision.

*Limitations and Conditions:*

1. Instructions for Continued Airworthiness – Emergency Medical Interior Aft Facing Fixed Seats Installation in Eurocopter Model BK-117 C-2 Aircraft, Report No. IC01012.1 Rev. A dated 8/16/2005 or later approved revision is required with the Aft Facing Fixed Seats installed.
2. Instructions for Continued Airworthiness – Emergency Medical Interior Translating Aft Facing Seat Installation in Eurocopter Model BK-117 C-2 Aircraft, Report No. IC01012.2 Rev. A dated 8/16/2005 or later approved revision is required with Translating Aft Facing Seat installed.
3. Instructions for Continued Airworthiness – Emergency Medical Interior Patient Loading System Installation in Eurocopter Model BK-117 C-2 Aircraft, Report No. IC01012.3 Rev. A dated 8/16/2005 or later approved revision is required with Patient Loading System (Primary Stretcher) installed.
4. Instructions for Continued Airworthiness – Emergency Medical Interior Secondary Stretcher Installation in Eurocopter Model BK-117 C-2 Aircraft, Report No. IC01012.4 Rev. A dated 8/16/2005 or later approved revision is required with Secondary Stretcher installed.

(See Continuation Sheet 2)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* May 27, 2005

*Date reissued:* April 20, 2009

*Date of issuance:* August 17, 2005

*Date amended:*



*By direction of the Administrator*

(Signature)

Anthony Socias  
Manager  
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* SR01968NY-D

Date of Issuance: August 17, 2005

Date of Reissuance: April 20, 2009

*Limitations and Conditions* (Continued).

5. FAA approved Rotorcraft Flight Manual Supplement, Supplement No. FM01012 Rev. – dated 8/17/2005 or later approved revision is required for this modification.
6. The installer must determine whether this design change is compatible with previously approved modifications.
7. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

.....END.....