

Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SA01847SE

This certificate, issued to **AeroMech Incorporated
1616 Hewitt Ave., Suite 312
Everett, WA 98201**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: A38CE, Rev. 11
Make: Hawker Beechcraft
Model: 2000, Serial Number NC-33

Description of the Type Design Change: Non-group aircraft approval for Reduced Vertical Separation Minimum (RVSM), in accordance with AeroMech Document No. AMI-QD-B2000-0804, Rev. "NEW", dated May 19, 2008, (or latest FAA-approved revision).

Limitations and Conditions: Instructions for Initial and Continued Airworthiness, Document AMI-IICA-B2000-0806, Rev. "New", dated May 19, 2008, (or latest approved revision), is a required part of this STC.

The Airplane Flight Manual Supplement for the Hawker Beechcraft Model 2000, serial number NC-33, AeroMech Document AMI-AFMS-B2000-0806, Rev. "Original", FAA-approved May 28, 2008, (or latest approved revision), is required on-board for operation of the aircraft.

Descriptive data pertaining to this design change are considered inadequate for duplication on other products. This approval is limited to the Hawker Beechcraft Model 2000, serial number NC-33, only.

A copy of this certificate must be maintained as part of the permanent records of the aircraft. If the holder agrees to permit another person to use this certificate, the holder shall give the other person written evidence of the permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: May 13, 2008

Date reissued:

Date of issuance: June 11, 2008

Date amended:



By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.