

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA1224CE ✓

*This certificate issued to* Honeywell International Inc.  
23500 W. 105<sup>th</sup> Street  
Olathe, KS 66061

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product - Type Certificate Number:* T.C. No. A33EU  
*Make:* Avions Marcel Dassault-Breguet  
*Model:* Falcon 10

*Description of Type Design Change:*

Installation of King KFC 300 Dual Flight Director Flight Control System (Category II Configuration).  
REQUIRED DATA: 1. King Master Drawing 155-9063-00 Rev. 3, 6-17-76, and data referenced therein or later approved revision. 2. FAA Approved Flight Manual Supplement (Category II), dated 5-24-76, or later approved revisions.

*Limitations and Conditions:*

This approval should not be extended to other specific airplanes of this model on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of those previously approved modifications will introduce no adverse effect upon the airworthiness of that airplane.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* 2-17-76

*Date reissued:* 1-31-95; 2-28-00

*Date of issuance:* 6-18-76

*Date amended:*



*By direction of the Administrator*

*Chris Durkin*  
\_\_\_\_\_  
(Signature)  
for Chris Durkin  
DAS Coordinator, DAS-500863-CE

\_\_\_\_\_  
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.