

Supplemental Type Certificate

Number SR00121LA-D

This Certificate issued to **Heli-Support, Inc.**
120 N.E. Frontage Road
Ft. Collins, Colorado 80524

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part *06 of the Civil Air Regulations. *For Certification Basis See Type Certificate Data Sheet H1IN*

Original Product Type Certificate Number : H1IN

Make : Aerospatiale

Model : SA.315B, SA.316B and SE.3160

Description of Type Design Change: Installation for replacement starter/generator support bracket in accordance with Heli-Support, Inc. Master Document List No. 112-000, Revision B dated July 15, 1999, or later approved revisions required as part of these modifications.

Limitations and Conditions: The approval of this change in type design applies to the above noted model helicopters only. This approval should not be extended to other aircraft of this model on which other approved modifications are incorporated, unless it is determines that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this certificate and Approved Master Document List (MDL) No. 112-000, Revision B dated July 15, 1999, or later approved MDL, must be maintained as part of the permanent records of a helicopter modified in accordance with this STC. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : March 05, 1998

Date reissued: May 10, 2004; August 6, 2004;
October 31, 2006

Date of issuance : July 29, 1999

Date amended :

By direction of the Administrator



(Signature)

**Manager, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office**

(Title)

alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.